

**DOORS EXTERIOR**

1. DOOR 1 EXTERIOR TAKEN AT 2 METRES ON AXIS
2. DOOR 2 EXTERIOR BOTTOM HINGE DETAIL TAKEN AT 1 METRES ON AXIS
3. DOOR 2 EXTERIOR DOOR HANDLE DETAIL TAKEN AT 0.5 METRES ON AXIS
4. DOOR 2 EXTERIOR STONE DETAIL 1 TAKEN AT 0.5 METRES ON AXIS
5. DOOR 2 EXTERIOR STONE DETAIL 2 TAKEN AT 0.5 METRES ON AXIS
6. DOOR 2 EXTERIOR STONE DETAIL 3 TAKEN AT 0.5 METRES ON AXIS
7. DOOR 2 EXTERIOR TAKEN AT 2 METRES ON AXIS
8. DOOR 2 EXTERIOR TOP HINGE DETAIL TAKEN AT 1 METRES ON AXIS
9. DOOR 3 TAKEN AT 3 METRES ON AXIS

**WINDOOWS EXTERIOR**

10. WINDOW A AND PART OF B EXTERIOR TAKEN AT 2 METRES ON AXIS
11. WINDOWS B AND C EXTERIOR TAKEN AT 2 METRES ON AXIS
12. WINDOW D EXTERIOR TAKEN AT 2 METRES ON AXIS
13. WINDOW E EXTERIOR TAKEN AT 2 METRES
14. WINDOW F EXTERIOR TAKEN AT 2 METRES
15. WINDOWS E,F AND W EXTERIOR
16. WINDOW G EXTERIOR TAKEN AT 2 METRES
17. WINDOW H EXTERIOR TAKEN AT 2 METRES
18. WINDOW I EXTERIOR TAKEN AT 2 METRES
19. WINDOW J EXTERIOR TAKEN AT 2 METRES
20. WINDOW K EXTERIOR TAKEN AT 2 METRES
21. WINDOW L AND DOOR 3 EXTERIOR TAKEN AT 3 METRES
22. WINDOWS M, N AND O EXTERIOR TAKEN AT 5 METRES
23. WINDOWS M,N O, R AND S TAKEN AT 5 METRES
24. WINDOWS Q, R, S AND T TAKEN AT 5 METRES
25. WINDOW T CLOSE UP EXTERIOR TAKEN AT 3 METRES

**GENERAL EXTERIOR**

26. GENERAL VIEW OF SOUTH EAST FRONT WALL INCLUDING WINDOWS E, F AND W, DOOR 2 AND FRONT FENCE, TAKEN FROM COLLEGE GREEN ROAD.
27. GENERAL VIEW OF SOUTH EAST FACE TAKEN FROM COLLEGE GREEN ROAD
28. GENERAL VIEW OF NORTH EAST SIDE INCLUDING FRONT AND SIDE WALL
29. GENERAL VIEW OF SOUTH EAST FACING WALL INCLUDING WINDOW V AND DOOR 1
30. DOOR 1 AND WINDOW V EXTERIOR TAKEN AT 3 METRES ON AXIS
31. GENERAL VIEW OF SOUTH WEST SIDE TOWARD DOOR 1 SHOWING ROOF DETAIL TAKEN AT 10 METRES
32. GENERAL VIEW OF SOUTH WEST SIDE TOWARD DOOR 1 TAKEN AT 10 METRES
33. GENERAL VIEW OF SOUTH EAST FRONT FACE TAKEN AT 10 METRES
34. GENERAL VIEW OF DOOR 2 TAKEN AT 5 METRES
35. NAVE NORTH EAST WALL TAKEN FROM BASE OF TOWER

**GENERAL EXTERIOR CONTINUED**

36. GENERAL VIEW OF NAVE NORTH EAST WALL TAKEN FROM LANE AT 7 METRES
37. REAR OF TOWER AND PART OF NAVE NORTH EAST WALL TAKEN FROM IN FRONT OF WINDOW K
38. TOWER AND HEAD OF WINDOW G TAKEN FROM BASE GROUND LEVEL
39. TOWER CLOSE UP TAKEN FROM GROUND LEVEL IN FRONT OF WINDOW H
40. TOWER NORTH EAST SIDE TAKEN FROM LANE
41. ROOF DETAIL SOUTH WEST SIDE
42. TOILET AND VESTRY EXTERIOR NORTH WEST FACING TAKEN FROM LANE
43. GENERAL VIEW ACROSS NORTH WEST REAR WALL OF TOILET, VESTRY, REAR CORRIDOR, KITCHEN AND ASSEMBLY ROOM
44. BOILER HOUSE AT SOUTH WEST END OF ASSEMBLY ROOM SHOWING WINDOWS T AND X

**DOORS INTERIOR**

45. DOOR 1 BOTTOM CLOSED INTERIOR TAKEN AT 1 METRE ON AXIS
46. DOOR 1 TOP CLOSED INTERIOR TAKEN AT 1 METRE ON AXIS
47. DOOR 2 INTERIOR DOOR LOCK WITH FLASH TAKEN AT 0.5 METRES ON AXIS
48. DOOR 2 INTERIOR DOOR LOCK WITHOUT FLASH TAKEN AT 0.5 METRES ON AXIS
49. DOOR 2 INTERIOR TAKEN THROUGH ENTRANCE LOBBY INNER DOOR 11 AT 2 METRES
50. DOOR 2 OPEN INTERIOR LATCH TAKEN AT 0.5 METRES ON AXIS
51. DOOR 3 INTERIOR TAKEN FROM DOORWAY 4 AT 1 METRE
52. DOOR 3 LATCH AND LOCK TAKEN FROM 0.5 METRES ON AXIS
53. DOOR 4 AND WINDOW L INTERIOR TAKEN FROM DOOR 6 AT 3 METRES
54. DOOR 5 CLOSED INTERIOR TAKEN AT 3 METRE ON AXIS
55. DOOR 6 CLOSED INTERIOR ORGAN SIDE TAKEN AT 3 METRE ON AXIS
56. DOOR 6 CLOSED INTERIOR VESTRY SIDE FROM DOOR 4 TAKEN AT 1 METRE ON AXIS
57. DOOR 6 CLOSED INTERIOR VESTRY SIDE TAKEN AT 2 METRES FROM DOOR 4
58. DOOR 7 CLOSED INTERIOR FROM KITCHEN SIDE TAKEN AT 2 METRES FROM DOOR 8
59. DOOR 7 CLOSED INTERIOR FROM ORGAN PASSAGE TAKEN AT 3 METRE ON AXIS
60. DOOR 7 OPEN INTERIOR KITCHEN SIDE TAKEN AT 1 METRE ON AXIS
61. DOOR 8 CLOSED INTERIOR FROM KITCHEN SIDE TAKEN FROM DOOR 7 AT 2 METRES
62. DOOR 8 CLOSED INTERIOR TAKEN FROM ASSEMBLY ROOM SIDE AT 3 METRE ON AXIS
63. DOOR 9 BOTTOM CLOSED INTERIOR WITH FLASH TAKEN AT 1 METRE ON AXIS
64. DOOR 9 TOP CLOSED INTERIOR WITHOUT FLASH TAKEN AT 1 METRE ON AXIS
65. DOOR 10 CLOSED INTERIOR ASSEMBLY ROOM SIDE TAKEN AT 2 METRES ON AXIS
66. DOOR 10 CLOSED INTERIOR CHURCH SIDE TAKEN AT 3 METRES ON AXIS
67. DOOR 10 OPEN INTERIOR TAKEN ON CHURCH SIDE AT 3 METRES ON AXIS
68. DOOR 11 CLOSED REAR INTERIOR TAKEN AT 2 METRE ON AXIS
69. DOOR 11 CLOSED FRONT INTERIOR TAKEN AT 2 METRES ON AXIS
70. DOOR 11 CLOSED FRONT INTERIOR TAKEN AT 3 METRES ON AXIS
71. DOOR 11 OPEN SHOWING REAR OF EXTERIOR DOOR 2 TAKEN AT 3 METRES OFF AXIS
72. DOOR 11 OPEN INTERIOR TAKEN AT 2 METRES ON AXIS

**WINDOWS INTERIOR**

73. WINDOW A INTERIOR TAKEN AT 3 METRES ON AXIS
74. WINDOW B INTERIOR TAKEN AT 3 METRES ON AXIS
75. WINDOW C INTERIOR TAKEN AT 3 METRES ON AXIS
76. WINDOW D INTERIOR TAKEN AT 3 METRES ON AXIS
77. WINDOWS A, B, C & D INTERIOR TAKEN FROM 1 METRE IN FRONT OF WINDOW D ON AXIS
78. WINDOWS A, B, C & D INTERIOR TAKEN NEXT TO THE PULPIT AND ORGAN
79. WINDOW F TAKEN AT 3 METRES ON AXIS
80. WINDOW E INTERIOR TAKEN ON AXIS AT 4 METRES
81. WINDOWS E & F TAKEN ON AXIS BETWEEN THEM AT 4 METRES
82. WINDOW F INTERIOR TAKEN ON AXIS AT 4 METRES
83. ROSE WINDOW AND ARCHED WINDOWS E AND F TAKEN FROM 6 METRES ON AXIS CENTRE OF NAVE
84. ROSE WINDOW W CLOSE UP DETAIL TAKEN FROM CENTRE OF CHURCH 6 METRES.
85. ROSE WINDOW W FRONT CLOSE UP INTERIOR
86. WINDOW G DETAIL TAKEN FROM 1.5 METRES ON AXIS
87. WINDOW G DETAIL TAKEN FROM 1.5 METRES ON AXIS
88. WINDOW H INTERIOR TAKEN AT 3 METRES ON AXIS
89. WINDOW I INTERIOR TAKEN AT 3 METRES ON AXIS
90. WINDOWS J & K INTERIOR TAKEN AT 3 METRES ON AXIS
91. WINDOWS H, I, J & K INTERIOR TAKEN NEXT TO ENTRANCE VESTIBULE DOOR 11
92. WINDOWS S & R INTERIOR TAKEN AT 3 METRES ON AXIS
93. WINDOW U & V INTERIOR TAKEN AT 3 METRES ON AXIS
94. WINDOWS U & V INTERIOR TAKEN AT 3 METRES ON AXIS
95. WINDOWS R & Q INTERIOR TAKEN AT 3 METRES ON AXIS
96. WINDOW U INTERIOR TAKEN AT 2 METRES ON AXIS
97. WINDOW T ASSEMBLY ROOM INTERIOR TAKEN 2 METRES ON AXIS
98. WINDOW L VESTRY INTERIOR TAKEN AT 2 METRES ON AXIS
99. WINDOW N VESTRY INTERIOR TAKEN AT 2 METRES ON AXIS
100. WINDOW P KITCHEN INTERIOR TAKEN AT 2 METRES ON AXIS

**GENERAL INTERIOR**

101. ASSEMBLY ROOM TAKEN FROM BELOW ROUND WINDOW TOWARDS ENTRANCE PORCH 7 METRES
102. ASSEMBLY ROOM TAKEN FROM ENTRANCE PORCH END TOWARDS ROUND WINDOW 7 METRES
103. ASSEMBLY ROOM CEILING TAKEN FROM BELOW ROUND WINDOW AT 7 METRES
104. ASSEMBLY ROOM CEILING TAKEN FROM ENTRANCE PORCH END SHOWING ROOF VENT TAKEN AT 7 METRES
105. ASSEMBLY ROOM TRUSS SUPPORT CLOSE UP
106. ASSEMBLY ROOM TRUSS SUPPORT DETAIL
107. ASSEMBLY ROOM ROUND WINDOW
108. ASSEMBLY ROOM ENTRANCE PORCH WITH OPEN DOOR TAKEN FROM CENTRE OF ASSEMBLY ROOM AT 3 METRES

**GENERAL INTERIOR CONTINUED**

109. ASSEMBLY ROOM ENTRANCE PORCH, ASSEMBLY ROOM INTERIOR SIDE TAKEN AT 3 METRES
110. ASSEMBLY ROOM NORTH WEST FACING WALL INTERIOR 1 TAKEN AT 3 METRES
111. ASSEMBLY ROOM NORTH WEST FACING WALL INTERIOR 2 TAKEN AT 3 METRES
112. ASSEMBLY ROOM PARQUET FLOOR DETAIL TAKEN FROM CENTRE OF ROOM TOWARD ROUND WINDOW END FROM 4 METRES
113. ASSEMBLY ROOM SHOWING OPEN PORCH DOOR AND VIEW TO KITCHEN TAKEN FROM SOUTH EAST WALL AT 4 METRES
114. ASSEMBLY ROOM SOUTH EAST FACING WALL INTERIOR 1 TAKEN AT 3 METRES
115. ASSEMBLY ROOM SOUTH EAST FACING WALL INTERIOR 2
116. ASSEMBLY ROOM WALL AIR VENT COVER DETAIL TAKEN AT 1 METRE ON AXIS
117. ASSEMBLY ROOM ROOF VENT DETAIL TAKEN AT 3 METRES BELOW
118. ASSEMBLY ROOM PORCH CIELING DETAIL 1 WITH FLASH AT 1 METRE
119. ASSEMBLY ROOM PORCH CIELING DETAIL 2 WITH FLASH AT 1 METRE
120. ASSEMBLY ROOM PORCH FLOOR TILES AND HEATING GRILLE WITH FLASH TAKEN FROM 1 METRE
121. ASSEMBLY ROOM PORCH SHOWING COAT HOOKS TAKEN AT 1 METRE ON AXIS
122. KITCHEN CUPBOARDS TAKEN FROM SINK AT 2 METRES
123. KITCHEN LARGE CUPBOARD TAKEN FROM 2 METRES
124. KITCHEN SMALL CUPBOARD TAKEN FROM ASSEMBLY ROOM ENTRANCE DOORWAY AT 2 METRES
125. KITCHEN WIDE SHOT TAKEN FROM ASSEMBLY ROOM DOORWAY
126. MA127.MAIN ENTRANCE PORCH WINDOW, COAT HOOKS AND REAR OF DOOR 2, TAKEN FROM
127. MAIN ENTRANCE PORCH WINDOW, COAT HOOKS AND REAR OF DOOR 2, TAKEN FROM DOORWAY 11 AT 2 METRES
128. VIEW IN TO MAIN ENTRANCE PORCH THROUGH DOOR 11 TAKEN AT 2 METRES
129. REAR CORRIDOR CEILING HEATING PIPE REVERSE VIEW TAKEN AT 1 METRE
130. REAR CORRIDOR CEILING HEATING PIPE TAKEN AT 1 METRE
131. REAR CORRIDOR PAST ORGAN EQUIPMENT ROOM SHOWING AIR PIPES, TAKEN AT 3 METRES
132. VICTORIAN TOILET SEAT AND TILED FLOOR 2 TAKEN WITH FLASH AT 1 METRE
133. VICTORIAN TOILET SEAT AND TILED FLOOR TAKEN AT 1 METRE
134. VICTORIAN TOILET MANUFACTURERS DETAILS TAKEN AT 0.5 METRE
135. VICTORIAN SINK AND TAP TAKEN AT 1 METRE
136. VICTORIAN SINK AND TAP CLOSE UP TAKEN AT 0.5 METRE
137. VESTRY CEILING DETAIL FACING REAR CORRIDOR DOORWAY TAKEN AT 2 METRES
138. VESTRY CEILING DETAIL FACING TOILET DOORWAY TAKEN AT 2 METRES
139. VESTRY ENTRANCE PORCH COAT HOOKS TAKEN AT 1 METRE FROM DOORWAY
140. VESTRY ENTRANCE PORCH FLOOR TILES TAKEN AT 1 METRE WITH FLASH

**CHURCH INTERIOR DETAIL**

141. CEILING BEAMS TAKEN FROM BELOW ROSE WINDOW TOWARDS THE ORGAN
142. CEILING BEAMS TAKEN FROM IN FRONT OF ORGAN TOWARDS ROSE WINDOW
143. ROOF DETAIL WITH LIGHTS ON TAKEN FROM WINDOW K
144. NAVE ROOF BEAMS INTERSECTION POINT DETAIL
145. ROOF TRUSS SUPPORT WITH FLASH TAKEN AT 2 METRES 45 DEGREES OFF AXIS
146. ROOF TRUSS SUPPORTS, WINDOWS AND RADIATORS ON NORTH EASTERN WALL
147. NAVE HYMNAL
148. NAVE HYMNAL TOP SECTION WITH FLASH TAKEN AT 1 METRE ON AXIS
149. NAVE HYMNAL TOP SECTION WITHOUT FLASH TAKEN AT 1 M ON AXIS
150. NAVE HYMNAL CENTRE SECTION WITH FLASH TAKEN AT 1 M ON AXIS
151. NAVE HYMNAL CENTRE SECTION WITHOUT FLASH TAKEN AT 1 M ON AXIS
152. NAVE HYMNAL BOTTOM SECTION WITH FLASH TAKEN AT 1 M ON AXIS
153. NAVE HYMNAL BOTTOM SECTION WITHOUT FLASH TAKEN AT 1 M ON AXIS
154. ALTER CLOTH DETAIL TAKEN WITH FLASH AT 1 METRE ON AXIS
155. ALTER TOP AND LAMP TAKEN WITH FLASH AT 1 METRE ON AXIS
156. ALTER FRONT WITH FLASH TAKEN AT 45 DEGREES OFF AXIS 2 METRES
157. ALTER FRONT WITHOUT FLASH TAKEN AT 45 DEGREES OFF AXIS 2 METRES
158. ALTER RIGHT SIDE TAKEN FROM 2 METRES OFF AXIS
159. ALTER LEFT SIDE TAKEN 2 METRES OFF AXIS
160. ALTER DETAIL RIGHT SIDE 1 METRE.
161. PEW ON ALTER DIAS TO LEFT OF ALTER TAKEN AT 2 METRES ON AXIS
162. PEW ON ALTER DIAS TO RIGHT OF ALTER TAKEN AT 2 METRES ON AXIS
163. HOLOPHANE LAMP ABOVE THE ALTER TAKEN AT 3 METRES
164. HOLOPHANE LAMP IN CHURCH TAKEN AT 3 METRES
165. ORGAN TAKEN FROM 3RD PEW, CENTRE OF CHURCH 4 METRES ON AXIS
166. MAIN ORGAN PIPE ARRAY AS SEEN FROM ALTER LOOKING UP TAKEN AT 1 METRE
167. MAIN ORGAN PIPE ARRAY AS SEEN FROM LEFT AISLE TAKEN AT 3 METRES OFF AXIS
168. ORGAN ARCH SUPPORT DETAIL TAKEN AT 1 METRE WITH FLASH
169. ORGAN PIPE FRETWORK PANEL LEFT TAKEN AT 1 METRE
170. ORGAN PIPE FRETWORK PANELRIGHT TAKEN AT 1 METRE
171. ORGAN DUAL MANUAL WITH DOORS OPEN TAKEN AT 1 METRE
172. ORGAN DUAL MANUAL WITH DOORS CLOSED TAKEN AT 1 METRE
173. ORGAN DUAL MANUAL AND PEDALBOARD FROM ALTER WITH FLASH TAKEN AT 1 METRE
174. ORGAN DEDICATION PLAQUE AT BASE OF ORGAN PIPES
175. ORGAN DEDICATION PLAQUE CLOSE UP TAKEN AT .2 METRES ON AXIS
176. ORGANIST MEMORIAL PLAQUE TO LEFT OF ORGAN PIPES TAKEN AT 0.2 METRES ON AXIS
177. ELECTRONIC ACTUATOR ASSEMBLYS BEHIND ORGAN MANUAL BOX, TAKEN AT 1 METRE
178. REAR OF ORGAN MANUAL BOX TAKEN AT 2 METRES WITH FLASH
179. LARGE WOODEN PIPE ARRAY TAKEN FROM FLOOR LEVEL AT 1 METRE WITH FLASH
180. SMALLER WOODEN AND METAL PIPE ARRAYS AT FLOOR LEVEL, TAKEN AT 1 METRE WITH FLASH
181. REAR OF LARGE METAL PIPE ARRAY AS SEEN FROM ORGAN ROOM, WITH SOME FOREGROUND DETAIL OF AIRBOX PIPES, TAKEN AT 1 METRE WITH FLASH
182. SECONDARY METAL PIPE ARRAY TAKEN AT 1 METRE WITH FLASH
183. GRAFFITI DETAIL FOUND WRITTEN ON ORGAN ROOM DOOR FRAME

**CHURCH INTERIOR DETAIL CONTINUED**

- 184. VIEW OF PEWS TAKEN FROM DOORWAY 10
- 185. PEWS TAKEN FROM ALTER DIAS LEFT AISLE AT 2 METRES
- 186. PEW ENDS AS SEEN FROM AISLE AGAINST NORTH EAST WALL
- 187. PEW END DETAIL 1 TAKEN AT 1 METRE
- 188. PEWS IN FRONT OF DOOR 11
- 189. PEW END DETAIL 2 TAKEN AT 1 METRE SHOWING FLOOR BELOW CARPET
- 190. PEW REAR DETAIL SHOWING FLOORBOARDS BELOW CARPET TAKEN AT 1 METRE
- 191. LECTERN AND ORGAN TAKEN FROM CENTRE OF NAVE 5 METRES ON AXIS
- 192. NAVE TAKEN FROM BENEATH ROSE WINDOW W TOWARDS ORGAN
- 193. MAIN NAVE TAKEN FROM LECTERN TOWARD ROSE WINDOW
- 194. RADIATORS AND WINDOWS ALONG NORTH WEST WALL
- 195. PEWS AND WINDOWS ALONG NORTH EAST WALL