




Photographic Schedule North Wales Hospital




for

Denbighshire County Council,
Smithfield Road,
Denbigh,
LL16 3RJ

Ref: 168119/main range Elevation N

Date of Inspection: 28th Sept 2018

Ref	Photo	Comments
1		
2		No supporting drawings to reference.
3		Unable to survey

4	 A close-up photograph of a stone wall. A window with a wooden frame is visible, showing some internal structure. Below the window, there is a large, dark, irregular opening. The wall is covered in graffiti, including the letters 'AB' and some other markings. The wall appears to be made of rough, grey stone.	
5	 A photograph of a stone building with a damaged roof. The building is made of grey stone and has several windows. The roof is partially collapsed, and there is a large, dark, irregular opening in the roofline. The building is surrounded by greenery.	Roof destroyed by fire
6	 A photograph of a stone wall with a window and a chimney. The wall is made of grey stone and has a large, dark, irregular opening. A chimney is visible on the left side of the wall. The wall appears to be made of rough, grey stone.	Partial demolition